

## Gagemaker T072 | 7° X 45° Buttress Series Contact Points | Pitch 8

The pitch diameter of machined parts with 7° X 45° Buttress thread forms is checked using these contact points. For the majority of gauges, two are needed.

×

Specifications	Details
Pitch	8

×